


## Practice Audiogram 3 - Key



AUDIOMETRIC SYMBOLS				
	AIR CONDUCTION		BONE CONDUCTION	
	UNMASKED	MASKED	UNMASKED	MASKED
RIGHT EAR	○	△	<	[
LEFT EAR	×	□	>	]

**Note:** Arrows indicate “no response” at the maximum limits of the audiometer.

### Audiometer Limits (dBHL) for Pure Tones

Air	Hz	Bone
110	500	65
110	1000	65
110	2000	65
110	3000	65
110	4000	65